



Installation Instructions For

2021+ VAG GOLF R MK8/TIGUAN R EA888 EVO4

KIT CONTENTS

NO.	DESCRIPTION	QTY
1	Intake Tube 100mm	1
2	Air Box	1
3	Air Box Cover	1
4	Front Air Scoop	1
4	M5 Bolt	2
5	M5 Spring Washer	2
6	M5 Washer	2
7	4 1/2 Clamp	1
8	4 1/4 Clamp	1
9	Turbo Adapter	1
10	M4 Bolt	4
11	101mm 115L Filter	1
12	89mm 115L Open Top Filter	1
13	M6 Bolt	2

Please Check the Contents of this box immediately.

Report any defective or missing parts to us or our dealer that you purchased this product from.

Before installing any parts of this system, please read the instructions thoroughly. If you have any questions regarding installation please contact the our dealer or local modified car factory.

Installing does require some mechanical skills. A qualified mechanic is always recommended.

※Do not attempt to install the intake system while the engine is hot.

The installation may require removal of radiator fluid line that may be hot.

MST Performance Auto Parts offers a limited lifetime warranty to the original purchaser against defects in materials and workmanship. Warranty claims must be handled through the dealer from which the item was purchased.

*All installation of parts must be performed by a trained professional.





Figure 1: Stock air box.



Figure 4: Remove the stock PCV and inlet tube



Figure 2: Loosen the clamp.



Figure 5: Remove the stock PCV hose.



Figure 3: Loosen the clamp.



Figure 6: Remove the stock air box and air scoop.




Figure 7: Install MST turbo adapter. (For golf mk8 r)



Figure 10: Install the MST silicone hose.




Figure 8: Install the MST front air scoop and tight the M5 bolt *2



Figure 11: Connect the recirculation hose.




Figure 9: Install the MST air box.




Figure 12: Install the MST tube and connet the 4mm hose.




Figure 13: Install the MST air filter.




Figure 14: Install the heat shield cover and tight the M4 bolts.



Figure 15: Congratulations! You have just completed the installation of this intake system. Periodically, check the alignment of the intake, normal wear and tear can cause nuts and bolts to come loose.