





HUB INSPECTION REPORT

BMW 520I 520I 2.0


























REPORT REFERENCE	6AGUN3FNN3	BRAND & MODEL	BMW 520I 520I 2.0 2012
ROAD TAX STATUS	UNAVAILABLE	HUB LOCATION	PJ, KLANG VALLEY
		CAR REG FRONT	Available
		CAR REG BACK	-
		ODOMETER	100298
		OUTSTANDING FINANCING	NO
		KEEP NUMBER	NO



✔ Normal Condition, No Abnormalities.
















✘ Abnormal or Damaged

⊖ Not Available/ Not Applicable

ROAD TEST		
ENGINE		
[1] ENGINE STARTING		
[2] ENGINE IDLING		
[3] ENGINE ACCELERATION		
[4] ENGINE NOISE		
TRANSMISSION, TRANSAXLE & CLUTCH		
[5] TRANSMISSION / TRANSAXLE SHIFT		
[6] TRANSMISSION / TRANSAXLE NOISE		
[7] SHIFT INTERLOCK OPERATION		
[8] DRIVE AXLE / TRANSFER CASE NOISE		
[9] CLUTCH OPERATION		
STEERING & BRAKE		
[10] STEERING OPERATION		
[11] UNDERCARRIAGE NOISE		
[12] ABS OPERATION		
[13] BRAKE OPERATION		
INTERIOR		
INTERIOR AMENITIES		
[14] CRUISE CONTROL OPERATION		
[15] METER AND GAUGES OPERATION		
[16] INDICATOR LIGHTS		
[17] WARNING LIGHT		
[18] MULTI FUNCTION DISPLAY		
[19] TRIPMETER AND ODOMETER		
[20] DRIVER/ MEMORY PROFILE SYSTEMS		
[21] CLOCK		
[22] TILT/TELESCOPIC STEERING WHEEL		
[23] STEERING COLUMN LOCK		
[24] MULTIFUNCTION STEERING WHEEL SWITCHES		
[25] POWER STEERING		
[26] HORN		
[27] INSTRUMENT CLUSTER		

[28] WINDSHIELD WIPERS SWITCH	<input checked="" type="checkbox"/>	
[29] WASHERS SWITCH	<input checked="" type="checkbox"/>	
[30] PADDLE SHIFTERS	<input type="checkbox"/>	
[31] INTERIOR COURTESY, DOME & MAP LIGHTS	<input checked="" type="checkbox"/>	
[32] REAR VIEW MIRRORS	<input checked="" type="checkbox"/>	
[33] AUTO-DIMMING REAR VIEW MIRROR	<input checked="" type="checkbox"/>	
[34] PARKING SENSORS/CAMERA	<input checked="" type="checkbox"/>	
[35] POWER OUTLETS	<input checked="" type="checkbox"/>	
[36] CIGGARATTE LIGHTER	<input checked="" type="checkbox"/>	
[37] ASHTRAYS	<input checked="" type="checkbox"/>	
[38] GEAR KNOB	<input checked="" type="checkbox"/>	
[39] HANDBRAKE / FOOTBRAKE LEVER	<input checked="" type="checkbox"/>	
[40] CENTER ARMREST/CONSOLE	<input checked="" type="checkbox"/>	
[41] SUN VISORS, VANITY MIRROR & LIGHT	<input checked="" type="checkbox"/>	
[42] STEERING WHEEL	<input checked="" type="checkbox"/>	
SAFETY BELTS		
[43] SAFETY BELTS	<input checked="" type="checkbox"/>	
AUDIO & ALARM SYSTEMS		
[44] AUDIO PLAYER	<input checked="" type="checkbox"/>	
[45] ANTENNA	<input checked="" type="checkbox"/>	
[46] ALARM/ THEFT-DETERRENT SYSTEM	<input checked="" type="checkbox"/>	
[47] SPEAKERS	<input checked="" type="checkbox"/>	
[48] REVERSE CAMERA	<input type="checkbox"/>	
HEAT, VENT, AC, DEFOG & DEFROST		
[49] AIR CONDITIONING SYSTEM	<input checked="" type="checkbox"/>	
[50] DEFOG/DEFROST	<input checked="" type="checkbox"/>	
[51] AIR CONDITIONING SWITCH PANEL	<input checked="" type="checkbox"/>	
[52] CENTRE CONSOLE	<input checked="" type="checkbox"/>	
[53] FRONT AIRCON VENTS	<input checked="" type="checkbox"/>	
[54] REAR AIRCON VENTS	<input checked="" type="checkbox"/>	
CARPET, TRIM & MATS		
[55] DASHBOARD	<input checked="" type="checkbox"/>	
[56] GLOVE BOX	<input checked="" type="checkbox"/>	
[57] INTERIOR CARPET	<input checked="" type="checkbox"/>	

[58] FLOOR MATS	<input checked="" type="checkbox"/>	
[59] FRONT RIGHT DOOR TRIM & DOOR PANELS	<input checked="" type="checkbox"/>	
[60] FRONT LEFT DOOR TRIM & DOOR PANELS	<input checked="" type="checkbox"/>	
[61] REAR RIGHT DOOR TRIM & DOOR PANELS	<input checked="" type="checkbox"/>	
[62] REAR LEFT DOOR TRIM & DOOR PANELS	<input checked="" type="checkbox"/>	
[63] RIGHT A-PILLAR TRIM	<input checked="" type="checkbox"/>	
[64] LEFT A-PILLAR TRIM	<input checked="" type="checkbox"/>	
[65] RIGHT B-PILLAR TRIM	<input checked="" type="checkbox"/>	
[66] LEFT B-PILLAR TRIM	<input checked="" type="checkbox"/>	
[67] RIGHT C-PILLAR TRIM	<input checked="" type="checkbox"/>	
[68] LEFT C-PILLAR TRIM	<input checked="" type="checkbox"/>	
[69] HEADLINING	<input checked="" type="checkbox"/>	
[70] DRIVER SEAT	<input checked="" type="checkbox"/>	LEATHER
[71] FRONT PASSENGER SEAT	<input checked="" type="checkbox"/>	LEATHER
[72] REAR SEAT	<input checked="" type="checkbox"/>	LEATHER
[73] 3RD ROW SEAT	<input type="checkbox"/>	
[74] FOLDING SEATS	<input type="checkbox"/>	
[75] HEATED SEATS	<input type="checkbox"/>	
[76] COOLED SEATS	<input type="checkbox"/>	
[77] LUGGAGE BOARD MATS	<input checked="" type="checkbox"/>	
[78] PARCEL SHELF/ SPEAKER BOARD	<input checked="" type="checkbox"/>	
[79] INTEGRATED CHILD SAFETY SEATS	<input type="checkbox"/>	
SUNROOF, MOONROOF, CONVERTIBLE TOP		
[80] SUNROOF/ MOONROOF	<input type="checkbox"/>	
[81] CONVERTIBLE TOP	<input type="checkbox"/>	
WINDOWS & DOOR LOCKS		
[82] REMOTE ENTRY SYSTEM	<input checked="" type="checkbox"/>	
[83] PUSH-BUTTON START SYSTEM	<input checked="" type="checkbox"/>	
[84] CENTRAL LOCKING SYSTEM	<input checked="" type="checkbox"/>	
[85] CHILD SAFETY LOCK	<input checked="" type="checkbox"/>	
[86] REMOTE BOOT RELEASE	<input checked="" type="checkbox"/>	
[87] FUEL CAP RELEASE	<input checked="" type="checkbox"/>	
[88] FRONT LEFT POWER WINDOW CONTROLS	<input checked="" type="checkbox"/>	
[89] FRONT RIGHT POWER WINDOW CONTROLS	<input checked="" type="checkbox"/>	

[90] REAR LEFT POWER WINDOW CONTROLS		
[91] REAR RIGHT POWER WINDOW CONTROLS		
LUGGAGE COMPARTMENT		
[92] LUGGAGE COMPARTMENT TRIM		
[93] CARGO NET		
[94] LUGGAGE COMPARTMENT LIGHT		
[95] VEHICLE JACK & TOOLKIT		
[96] SPARE TYRE SIZE/ TYPE & SIDEWALL INSP		
[97] SPARE TYRE TREAD DEPTH/ AIR PRESSURE		
EXTERIOR		
BODY PANELS & BUMPERS		
[98] CHASSIS OR ENGINE NUMBER TEMPERED		
[99] CUT AND JOIN VEHICLE		
[100] FRONT BUMPER		
[101] FRONT BONNET		
[102] FRONT BONNET SUPPORT		
[103] FRONT BONNET INSULATOR		
[104] EMBLEM		
[105] RIGHT FRONT FENDER		
[106] LEFT FRONT FENDER		
[107] RIGHT FRONT DOOR		
[108] LEFT FRONT DOOR		
[109] REAR BUMPER		
[110] LEFT REAR FENDER		
[111] RIGHT REAR FENDER		
[112] RIGHT REAR DOOR		
[113] LEFT REAR DOOR		
[114] REAR BONNET		
[115] MAJOR ACCIDENT VEHICLE		
[116] FLOOD SIGNS/DAMAGE		
DOORS, HOOD & BOOT		
[117] ROOF		
[118] FRONT BONNET RELEASE MECHANISM		
[119] FRONT GRILLE		

GLASS & OUTSIDE MIRRORS

[120] WINDSHIELD



[121] FRONT RIGHT WINDOW



[122] FRONT LEFT WINDOW



[123] REAR RIGHT WINDOW



[124] REAR LEFT WINDOW



[125] REAR WINDOW/TAILGATE GLASS



[126] WIPERS



[127] LEFT SIDE MIRROR



[128] RIGHT SIDE MIRROR



[129] FRONT LEFT ELECTRIC FOLDING MIRROR



[130] FRONT RIGHT ELECTRIC FOLDING MIRROR



[131] REAR WIPERS

**EXTERIOR LIGHTS**

[132] HEADLAMP



[133] FOG LAMP/ DAY TIME RUNNING LIGHT



[134] TURN SIGNAL LAMP



[135] TAILLAMP



[136] REVERSE LIGHT



[137] HAZARD LIGHTS



[138] AUTO ON/OFF LIGHTS

**RIM, TIRES & WHEELS**

[139] FRONT LEFT RIM CONDITION



[140] FRONT LEFT TYRE CONDITION



[141] FRONT LEFT WHEEL COVER & CENTRE CAP



[142] FRONT RIGHT RIM CONDITION



[143] FRONT RIGHT TYRE CONDITION



[144] FRONT RIGHT WHEEL COVER & CENTRE CAP



[145] REAR LEFT RIM CONDITION



[146] REAR LEFT TYRE CONDITION



[147] REAR LEFT WHEEL COVER & CENTRE CAP



[148] REAR RIGHT RIM CONDITION
























[149] REAR RIGHT TYRE CONDITION



[150] REAR RIGHT WHEEL COVER & CENTRE CAP



UNDERCARRIAGE		
FLUIDS		
[151] ENGINE OIL		
[152] COOLANT		
[153] TRANSMISSION/ TRANSAXLE AUTOMATIC FLUIDS		
[154] BRAKE FLUIDS		
[155] POWER STEERING FLUIDS		
[156] WINDSHIELD WASHER FLUIDS		
COOLING SYSTEM		
[157] RADIATOR		
[158] RADIATOR CAP		
[159] COOLING FANS		
[160] COOLANT RESERVIORTANK		
[161] HOSES, LINES & FITTINGS		
ELECTRICAL SYSTEM		
[162] STARTER OPERATION		
[163] BATTERY		
EXHAUST SYSTEM		
[164] EXHAUST SYSTEM CONDITION		
[165] SPLASH COVER		
TRANSMISSION, TRANSAXILE & DIFFERENTIAL		
[166] TRANSMISSION MOUNTS		
BRAKES		
[167] FRONT BRAKE PADS		
[168] REAR BRAKEPADS		
[169] BRAKE LINES, HOSES & FITTINGS		
SUSPENSION		
[170] SHOCK ABSORBER		
STEERING AND ALIGNMENT		
[171] RACK-AND-PINION, LINKAGE & BOOTS		
[172] WHEEL ALIGNMENT		
[173] POWER STEERING PUMP		
ENGINE		
[174] BELTS		
[175] WIRING		
[176] ENGINE MOUNTS		

Disclaimer: Our inspection report are based on what is seen and heard by our inspectors at the time of inspection. We do not guarantee or warranty any physical deterioration or mechanical/technical failures or defects which arise after the date of inspection. No judgement is made to the internal components of engine, transmission, driveline, electrical or any other systems that require dismantling to diagnose. Our inspection report does not cover the authentication of the components or specification of the vehicle. The mileage is reported as per the readings on the odometer and MUV provides no guarantee to the actual mileage of the vehicle.

Where Is As Is Basis