





























































HUB INSPECTION REPORT
MERCEDES-BENZ B200 1.6 (A) BLUEEFFI

REPORT REFERENCE	VBLU7NUAPP
ROAD TAX STATUS	UNAVAILABLE








BRAND & MODEL	MERCEDES-BENZ B200 1.6 (A) BLUEEFFI 2012
HUB LOCATION	PJ, KLANG VALLEY
CAR REG FRONT	Available
CAR REG BACK	-
ODOMETER	104156
OUTSTANDING FINANCING	NO
KEEP NUMBER	NO






































ROAD TEST		
ENGINE		
[1] ENGINE STARTING		
[2] ENGINE IDLING		
[3] ENGINE ACCELERATION		
[4] ENGINE NOISE		
TRANSMISSION, TRANSAXLE & CLUTCH		
[5] TRANSMISSION / TRANSAXLE SHIFT		
[6] TRANSMISSION / TRANSAXLE NOISE		
[7] SHIFT INTERLOCK OPERATION		
[8] DRIVE AXLE / TRANSFER CASE NOISE		
[9] CLUTCH OPERATION		
STEERING & BRAKE		
[10] STEERING OPERATION		
[11] UNDERCARRIAGE NOISE		
[12] ABS OPERATION		
[13] BRAKE OPERATION		
INTERIOR		
INTERIOR AMENITIES		
[14] CRUISE CONTROL OPERATION		
[15] METER AND GAUGES OPERATION		
[16] INDICATOR LIGHTS		
[17] WARNING LIGHT		
[18] MULTI FUNCTION DISPLAY		
[19] TRIPMETER AND ODOMETER		
[20] DRIVER/ MEMORY PROFILE SYSTEMS		
[21] CLOCK		
[22] TILT/TELESCOPIC STEERING WHEEL		
[23] STEERING COLUMN LOCK		
[24] MULTIFUNCTION STEERING WHEEL SWITCHES		
[25] POWER STEERING		
[26] HORN		
[27] INSTRUMENT CLUSTER		

[28] WINDSHIELD WIPERS SWITCH		
[29] WASHERS SWITCH		
[30] PADDLE SHIFTERS		
[31] INTERIOR COURTESY, DOME & MAP LIGHTS		
[32] REAR VIEW MIRRORS		
[33] AUTO-DIMMING REAR VIEW MIRROR		
[34] PARKING SENSORS/CAMERA		
[35] POWER OUTLETS		
[36] CIGGARATTE LIGHTER		
[37] ASHTRAYS		
[38] GEAR KNOB		
[39] HANDBRAKE / FOOTBRAKE LEVER		
[40] CENTER ARMREST/CONSOLE		
[41] SUN VISORS,VANITY MIRROR & LIGHT		
[42] STEERING WHEEL		
SAFETY BELTS		
[43] SAFETY BELTS		
AUDIO & ALARM SYSTEMS		
[44] AUDIO PLAYER		
[45] ANTENNA		
[46] ALARM/ THEFT-DETERRENT SYSTEM		
[47] SPEAKERS		
[48] REVERSE CAMERA		
HEAT, VENT, AC, DEFOG & DEFROST		
[49] AIR CONDITIONING SYSTEM		
[50] DEFOG/DEFROST		
[51] AIR CONDITIONING SWITCH PANEL		
[52] CENTRE CONSOLE		
[53] FRONT AIRCON VENTS		
[54] REAR AIRCON VENTS		
CARPET, TRIM & MATS		
[55] DASHBOARD		
[56] GLOVE BOX		
[57] INTERIOR CARPET		

[58] FLOOR MATS		
[59] FRONT RIGHT DOOR TRIM & DOOR PANELS		
[60] FRONT LEFT DOOR TRIM & DOOR PANELS		
[61] REAR RIGHT DOOR TRIM & DOOR PANELS		
[62] REAR LEFT DOOR TRIM & DOOR PANELS		
[63] RIGHT A-PILLAR TRIM		
[64] LEFT A-PILLAR TRIM		
[65] RIGHT B-PILLAR TRIM		
[66] LEFT B-PILLAR TRIM		
[67] RIGHT C-PILLAR TRIM		
[68] LEFT C-PILLAR TRIM		
[69] HEADLINING		
[70] DRIVER SEAT		LEATHER
[71] FRONT PASSENGER SEAT		LEATHER
[72] REAR SEAT		LEATHER
[73] 3RD ROW SEAT		
[74] FOLDING SEATS		
[75] HEATED SEATS		
[76] COOLED SEATS		
[77] LUGGAGE BOARD MATS		
[78] PARCEL SHELF/ SPEAKER BOARD		
[79] INTEGRATED CHILD SAFETY SEATS		
SUNROOF, MOONROOF, COVERTIBLE TOP		
[80] SUNROOF/ MOONROOF		
[81] CONVERTIBLE TOP		
WINDOWS & DOOR LOCKS		
[82] REMOTE ENTRY SYSTEM		
[83] PUSH-BUTTON START SYSTEM		
[84] CENTRAL LOCKING SYSTEM		
[85] CHILD SAFETY LOCK		
[86] REMOTE BOOT RELEASE		
[87] FUEL CAP RELEASE		
[88] FRONT LEFT POWER WINDOW CONTROLS		
[89] FRONT RIGHT POWER WINDOW CONTROLS		

[90] REAR LEFT POWER WINDOW CONTROLS		
[91] REAR RIGHT POWER WINDOW CONTROLS		
LUGGAGE COMPARTMENT		
[92] LUGGAGE COMPARTMENT TRIM		
[93] CARGO NET		
[94] LUGGAGE COMPARTMENT LIGHT		
[95] VEHICLE JACK & TOOLKIT		
[96] SPARE TYRE SIZE/ TYPE & SIDEWALL INSP		
[97] SPARE TYRE TREAD DEPTH/ AIR PRESSURE		
EXTERIOR		
BODY PANELS & BUMPERS		
[98] CHASSIS OR ENGINE NUMBER TEMPERED		
[99] CUT AND JOIN VEHICLE		
[100] FRONT BUMPER		
[101] FRONT BONNET		
[102] FRONT BONNET SUPPORT		
[103] FRONT BONNET INSULATOR		
[104] EMBLEM		
[105] RIGHT FRONT FENDER		
[106] LEFT FRONT FENDER		
[107] RIGHT FRONT DOOR		
[108] LEFT FRONT DOOR		
[109] REAR BUMPER		
[110] LEFT REAR FENDER		
[111] RIGHT REAR FENDER		
[112] RIGHT REAR DOOR		
[113] LEFT REAR DOOR		
[114] REAR BONNET		
[115] MAJOR ACCIDENT VEHICLE		
[116] FLOOD SIGNS/DAMAGE		
DOORS, HOOD & BOOT		
[117] ROOF		
[118] FRONT BONNET RELEASE MECHANISM		
[119] FRONT GRILLE		

GLASS & OUTSIDE MIRRORS		
[120] WINDSHIELD		
[121] FRONT RIGHT WINDOW		
[122] FRONT LEFT WINDOW		
[123] REAR RIGHT WINDOW		
[124] REAR LEFT WINDOW		
[125] REAR WINDOW/TAILGATE GLASS		
[126] WIPERS		
[127] LEFT SIDE MIRROR		
[128] RIGHT SIDE MIRROR		
[129] FRONT LEFT ELECTRIC FOLDING MIRROR		
[130] FRONT RIGHT ELECTRIC FOLDING MIRROR		
[131] REAR WIPERS		
EXTERIOR LIGHTS		
[132] HEADLAMP		
[133] FOG LAMP/ DAY TIME RUNNING LIGHT		
[134] TURN SIGNAL LAMP		
[135] TAILLAMP		
[136] REVERSE LIGHT		
[137] HAZARD LIGHTS		
[138] AUTO ON/OFF LIGHTS		
RIM, TIRES & WHEELS		
[139] FRONT LEFT RIM CONDITION		
[140] FRONT LEFT TYRE CONDITION		
[141] FRONT LEFT WHEEL COVER & CENTRE CAP		
[142] FRONT RIGHT RIM CONDITION		
[143] FRONT RIGHT TYRE CONDITION		
[144] FRONT RIGHT WHEEL COVER & CENTRE CAP		
[145] REAR LEFT RIM CONDITION		
[146] REAR LEFT TYRE CONDITION		
[147] REAR LEFT WHEEL COVER & CENTRE CAP		
[148] REAR RIGHT RIM CONDITION		
[149] REAR RIGHT TYRE CONDITION		
[150] REAR RIGHT WHEEL COVER & CENTRE CAP		

UNDERCARRIAGE		
FLUIDS		
[151] ENGINE OIL		
[152] COOLANT		
[153] TRANSMISSION/ TRANSAXLE AUTOMATIC FLUIDS		
[154] BRAKE FLUIDS		
[155] POWER STEERING FLUIDS		
[156] WINDSHIELD WASHER FLUIDS		
COOLING SYSTEM		
[157] RADIATOR		
[158] RADIATOR CAP		
[159] COOLING FANS		
[160] COOLANT RESERVIO RTANK		
[161] HOSES, LINES & FITTINGS		
ELECTRICAL SYSTEM		
[162] STARTER OPERATION		
[163] BATTERY		
EXHAUST SYSTEM		
[164] EXHAUST SYSTEM CONDITION		
[165] SPLASH COVER		
TRANSMISSION, TRANSAXILE & DIFFERENTIAL		
[166] TRANSMISSION MOUNTS		
BRAKES		
[167] FRONT BRAKE PADS		
[168] REAR BRAKEPADS		
[169] BRAKE LINES, HOSES & FITTINGS		
SUSPENSION		
[170] SHOCK ABSORBER		
STEERING AND ALIGNMENT		
[171] RACK-AND-PINION, LINKAGE & BOOTS		
[172] WHEEL ALIGNMENT		
[173] POWER STEERING PUMP		
ENGINE		
[174] BELTS		
[175] WIRING		
[176] ENGINE MOUNTS		

Disclaimer: Our inspection report are based on what is seen and heard by our inspectors at the time of inspection. We do not guarantee or warranty any physical deterioration or mechanical/technical failures or defects which arise after the date of inspection. No judgement is made to the internal components of engine, transmission, driveline, electrical or any other systems that require dismantling to diagnose. Our inspection report does not cover the authentication of the components or specification of the vehicle. The mileage is reported as per the readings on the odometer and MUV provides no guarantee to the actual mileage of the vehicle.

Where Is As Is Basis