



Inspection Report

210-Point Vehicle Inspection Report

Location: **Seri Kembangan**

Report ID: **ATY5GU**

Vehicle Information


Mileage	112397 KM
Model & Variant	BMW 320i 2014
Transmission	Auto
Body Type	Sedan
Fuel Type	Petrol
Capacity	1997
Key Set	-

Remarks & Summary

Inspection Remarks

-We do not guarantee mileage authenticity -B5 will be done to verify Chassis & engine number -Onsite inspection - limited access

Vehicle Photos





















Exterior



Structure



Engine Bay



Interior




Undercarriage



Test Drive

Exterior Area

1 – FRONT WINDSCREEN, WIPERS & WASHERS	✓
2 – WINDSHIELD DRAIN	✓
3 – FRONT BONNET	✓
4 – FRONT REINFORCEMENT	✓


5 — FRONT GRILLE	
6 — FRONT BUMPER	
7 — FRONT SKIRT	N/A
8 — RHS HEADLAMP & DAY RUNNING LAMP	
9 — LHS HEADLAMP & DAY RUNNING LAMP	
10 — RHS FOGLAMP	
11 — LHS FOGLAMP	
12 — RHS FRONT FENDER	
13 — RHS SIGNAL INDICATOR	
14 — RHS A PILLAR	
15 — RHS ROOF PILLAR	
16 — RHS FRONT WINDOW & QUARTER GLASS	
17 — RHS SIDE MIRROR & SIGNAL INDICATOR  SCRATCHED	
18 — RHS FRONT DOOR & MOULDING	
19 — RHS FRONT DOOR HANDLE	
20 — RHS B PILLAR	
21 — RHS SIDE SILL	
22 — RHS SKIRT / SIDE STEP (PICKUP)	
23 — RHS REAR WINDOW & QUARTER GLASS	
24 — RHS REAR DOOR / SLIDING DOOR & MOULDING	
25 — RHS REAR DOOR HANDLE	
26 — RHS C PILLAR	
27 — RHS REAR QUARTER GLASS	
28 — RHS D PILLAR	N/A
29 — FUEL FILLER DOOR	
30 — RHS REAR FENDER / CARGO (PICKUP)  SCRATCHED	
31 — MOONROOF / SUNROOF	N/A
32 — ROOF & ANTENNA	

33 — SPOILER	N/A
34 — RHS ROOF DRIP	✓
35 — LHS ROOF DRIP	✓
36 — REAR WINDSCREEN, WIPERS & WASHERS	✓
37 — PARCEL SHELF (PICKUP)	N/A
38 — TONNEAU COVER / HARD TOP	N/A
39 — REAR BONNET / TAILGATE (PICKUP)	✓
40 — REAR REINFORCEMENT	N/I
41 — REAR LIGHTNING PANEL (PICKUP)	N/A
42 — REAR BUMPER	✓
43 — REAR SKIRT	✓
44 — RHS COMBINATION LAMP	✓
45 — LHS COMBINATION LAMP	✓
46 — LHS REAR FENDER / CARGO (PICKUP)	✓
47 — LHS D PILLAR	N/A
48 — LHS REAR QUARTER GLASS	N/A
49 — LHS C PILLAR	✓
50 — LHS REAR DOOR HANDLE	✓
51 — LHS REAR DOOR / SLIDING DOOR & MOULDING	✓
52 — LHS REAR WINDOW & QUARTER GLASS	✓
53 — LHS SKIRT / SIDE STEP (PICKUP)	✓
54 — LHS SIDE SILL	✓
55 — LHS B PILLAR	✓
56 — LHS FRONT DOOR HANDLE	✓
57 — LHS FRONT DOOR & MOULDING	✓
58 — LHS SIDE MIRROR & SIGNAL INDICATOR	✓
59 — LHS FRONT WINDOW & QUARTER GLASS	✓
60 — LHS ROOF PILLAR	✓

61 — LHS A PILLAR	
62 — LHS SIGNAL INDICATOR	
63 — LHS FRONT FENDER	
64 — TYRES	
65 — SPARE TYRE	N/A

Exterior Area Diagram

 Normal  Abnormal N/A Not Available N/I Not Inspected



17